

FIGURE 5.—Damaged CE 135 windshield removed from the Presidential limousine, front view.



C.E. 399 8/23/78




FIGURE 6A. CE 399, the fired 6.5-millimeter caliber full metal jacketed bullet found on a stretcher in the emergency area of Parkland Memorial Hospital, side view.

liber Mannlicher-Carcano rifle, serial  
left side.

**EVIDENCE**

POLICE DEPT. WASH. D.C. 20001  
SCENE EXAMINATION SECTION

cartridge of Western Cartridge Co  
chamber of CE 139 rifle.

HSCA VII

386




FIGURE 6B.—CE 399, the fired 6.5-millimeter caliber full metal-jacketed bullet found on a stretcher in the emergency area of Parkland Memorial Hospital, view of the base portion, showing distortion.



FIGURE 7.—CE 542, a 6.5 millimeter caliber Mannlicher-Careano rifle, serial No. UC 5209, purchased by the FBI for comparison purposes.




FIGURE 8A.—CE 543, one of three expended of Western Cartridge Co. manufacture, re Texas School Book Depository, side view.




FIGURE 8B.—CE 543, one of three expended of Western Cartridge Co. manufacture, re Texas School Book Depository, top view.